Technical Communications > Radio Trouble Report > RTR

Radio Trouble Report: RTR

🖹 New Item | 📝 Edit Item | ✖ Delete Item | Alert Me

Officer / Member:	PO MATTHEW BONGARD
MPD Email Address	
Work Location:	83
Squad #	831
Vehicle #	529
Radio #/Console position	
Location when problem arises?	
Date / Time of Issue:	6/5/2009 11:30 AM
District of occurrence	
Device Type:	Mobile Radio
Xmit/Rec Issue:	Both
Audio	
Transmit Tone:	
Receive Tones	
Control Light Issue:	
Antenna	No Antenna Symbol
Radio:	Turns On
Transmissions:	Will Not Receive
Problem Frequency	Intermittent
Problem Seems:	Non Location Dependent
Narrative:	THE RADIO LOSES ITS ANTENNA SIGNAL. I WILL HEAR A DOUBLE BEEP AND THE RADIO CONTROL HEAD WILL NO HAVE THE ANTENNA SYMBOL. I AM UNABLE TO TRANSMIT OR RECEIVE CALLS ON ANY CHANNELS. THE DOUBLE BEEP CONTINUES EVERY FEW SECONDS. THE ONLY WAY TO CORRECT THE PROBLEM IS TO TURN THE RADIO OFF AND WAIT FOR IT TO SHUT DOWN. THEN WHEN YOU TURN THE RADIO BACK ON YOU HAVE TO WAIT AGAIN FOR A FEW SECONDS FOR THE RADIO TO REBOOT. THESE FEW SECONDS COULD BE AN ISSUE OF EMERGENCY. THIS PROBLEM HAS OCCURED 3 TIMES PRIOR TO TODAY.

Title	RTR
Reviewed By:	ETS DAVID GO
Reviewed Date:	
Assigned To	
Due Date	
Comments	
Related Issues	
Issue Status	

Summary Overview

Created at 3/28/2010 9:19 AM by Zaworski,Mathew
Last modified at 3/28/2010 9:19 AM by Zaworski,Mathew