

Technical Communications

Technical Communications > Radio Trouble Report > RTR

Radio Trouble Report: RTR

Officer / Member:	Frank VRTOCHNICK
APD Email Address	fvrtoc@milwaukee.gov
Work Location:	22
Squad #	2281
/ehicle #	278
Radio #/Console position	
Location when problem arises?	
Date / Time of Issue:	4/7/2010 4:00 PM
District of occurrence	•
Device Type:	Console Radio
Xmit/Rec Issue:	Both
Audio	Intermittent
Transmit Tone:	Single Beep
Receive Tones	Beep every 5 seconds
Control Light Issue:	Doesn't Light Up
Antenna	No Antenna Symbol
Radio:	Turns On
Transmissions:	Neither Receive / Transmit
Problem Frequency	Continuous
Problem Seems:	Non Location Dependent
Narrative:	Radio recieved a continuous beep every 5 seconds no mater location. Radio showed no atenna symbol on display screen, no matter the location. Battery was fully charged.
Title	RTR
Reviewed By:	Captain Andra Williams
Reviewed Date:	4/8/2010 7:10 AM

Due Date

Duc muce	
Comments	Please send this radio to the radio shop to have its antenna checked.
Related Issues	
Issue Status	
Summary Overview	

Created at 4/7/2010 7:43 PM by Vrtochnick,Frank Last modified at 4/19/2010 10:35 AM by Williams, Andra P