

MILWAUKEE POLICE DEPARTMENT
Communications Division



Technical
 Communications

Technical Communications > Radio Trouble Report > (no title)

Radio Trouble Report: (no title)

New Item | Edit Item | Delete Item | Alert Me

Officer / Member: John IVY

MPD Email Address

Work Location: 72

Squad # 7230

Vehicle # 031

Radio #/Console position

Location when problem arises?

Date / Time of Issue: 2/3/2010 6:00 PM

District of occurrence

Device Type: Mobile Radio

Xmit/Rec Issue: Transmit

Audio

Transmit Tone: 3 Beeps

Receive Tones

Control Light Issue: Doesn't Light Up

Antenna No Antenna Symbol

Radio: Turns On

Transmissions: Will Not Transmit

Problem Frequency Intermittent

Problem Seems: Non Location Dependent

Narrative: PO John IVY and PO Scott DAVIS were engaged in a foot chase with a suspect, who we beleived may have been armed at I could not transmit pertinent chase information. Upon confronting the suspect, the suspect demanded that i, while not showing his hands. This was a possible scenario that I was not able to broadcast due to the radio hardware. I recived several 3 beep tones, and a quck double tone. Thankfully he suspect was able to be taken into custody safelt and without major incident. It wasnt until the entire footchase and arrest procedure was over that my partner was able to use his working radio to transmit pertinent information to the dispatcher. The failure of this equipment

did not allow me to apprise the dispatcher of the development of a possible critical incident, which was necessary to preserve officer and subject safety.

Title

Reviewed By:

Reviewed Date:

Assigned To

Due Date

Comments

Related Issues

Issue Status

Summary Overview

Created at 2/26/2010 10:08 AM by Zaworski, Mathew
Last modified at 2/26/2010 11:38 AM by Williams, Andra P