



Technical  
Communications

Technical Communications > Radio Trouble Report > RTR

## Radio Trouble Report: RTR

| 
  | 
  |

<b>Officer / Member:</b>	PO David Gabbard
<b>MPD Email Address</b>	
<b>Work Location:</b>	74
<b>Squad #</b>	7467
<b>Vehicle #</b>	171
<b>Radio #/Console position</b>	
<b>Location when problem arises?</b>	
<b>Date / Time of Issue:</b>	1/6/2010 9:00 PM
<b>District of occurrence</b>	
<b>Device Type:</b>	Portable Radio
<b>Xmit/Rec Issue:</b>	Transmit
<b>Audio</b>	Intermittent
<b>Transmit Tone:</b>	Single Beep
<b>Receive Tones</b>	
<b>Control Light Issue:</b>	
<b>Antenna</b>	
<b>Radio:</b>	
<b>Transmissions:</b>	Will Not Transmit
<b>Problem Frequency</b>	Continuous
<b>Problem Seems:</b>	Location Dependent
<b>Narrative:</b>	At the intersection of _____ the handheld radio emits a single long tone or beep when the mic transmit key is pressed. I moved my position several feet east, then west, and finally north (now on the sidewalk) and I was able to transmit and provide dispatch with an answer to their question of needed another car at the time. My partner's handheld (8160) did not broadcast the dispatch's acknowledgement of our assignment or Disatches inquiry as to needing another car. CAD#10-006-2000
<b>Title</b>	RTR
<b>Reviewed By:</b>	

**Reviewed Date:**

**Assigned To**

**Due Date**

**Comments**

**Related Issues**

**Issue Status**

**Summary Overview**

Created at 3/1/2010 8:49 AM by Zaworski,Mathew  
Last modified at 3/1/2010 8:49 AM by Zaworski,Mathew