



Technical  
Communications

Technical Communications > Radio Trouble Report > RTR

## Radio Trouble Report: RTR

<input type="button" value="New Item"/>   <input type="button" value="Edit Item"/>   <input type="button" value="Delete Item"/>   <input type="button" value="Alert Me"/>	
<b>Officer / Member:</b>	PO Matt DIENER
<b>MPD Email Address</b>	
<b>Work Location:</b>	22
<b>Squad #</b>	2220
<b>Vehicle #</b>	--
<b>Radio #/ Console position</b>	
<b>Location when problem arises?</b>	
<b>Date / Time of Issue:</b>	1/4/2010 6:00 PM
<b>District of occurrence</b>	
<b>Device Type:</b>	Portable Radio
<b>Xmit/Rec Issue:</b>	Both
<b>Audio</b>	
<b>Transmit Tone:</b>	
<b>Receive Tones</b>	
<b>Control Light Issue:</b>	
<b>Antenna</b>	
<b>Radio:</b>	
<b>Transmissions:</b>	Neither Receive / Transmit
<b>Problem Frequency</b>	
<b>Problem Seems:</b>	
<b>Narrative:</b>	Radio head connector detached by itself has multiple broken prongs.
<b>Title</b>	RTR
<b>Reviewed By:</b>	
<b>Reviewed Date:</b>	
<b>Assigned To</b>	
<b>Due Date</b>	

**Comments**

---

**Related Issues**

---

**Issue Status**

---

**Summary Overview**

Created at 3/1/2010 12:03 PM by Zaworski,Mathew  
Last modified at 3/1/2010 12:03 PM by Zaworski,Mathew