



Technical  
Communications

Technical Communications > Radio Trouble Report > RTR

## Radio Trouble Report: RTR

| 
  | 
  |

<b>Officer / Member:</b>	Robert King Jr.
<b>MPD Email Address</b>	rking@milwaukee
<b>Work Location:</b>	40
<b>Squad #</b>	4015
<b>Vehicle #</b>	4000
<b>Radio #/Console position</b>	
<b>Location when problem arises?</b>	
<b>Date / Time of Issue:</b>	4/13/2010 4:30 PM
<b>District of occurrence</b>	
<b>Device Type:</b>	Console Radio
<b>Xmit/Rec Issue:</b>	Both
<b>Audio</b>	
<b>Transmit Tone:</b>	
<b>Receive Tones</b>	
<b>Control Light Issue:</b>	
<b>Antenna</b>	
<b>Radio:</b>	Turns On
<b>Transmissions:</b>	
<b>Problem Frequency</b>	
<b>Problem Seems:</b>	Location Dependent
<b>Narrative:</b>	Upon patching 2 channels, the added channel failed to operate at each Dispatcher console.
<b>Title</b>	RTR
<b>Reviewed By:</b>	Captain Andra Williams
<b>Reviewed Date:</b>	4/13/2010 4:10 PM
<b>Assigned To</b>	
<b>Due Date</b>	

**Comments**

---

**Related Issues**

---

**Issue Status**

---

**Summary Overview**

Created at 4/14/2010 6:15 PM by King Jr., Robert  
Last modified at 4/19/2010 11:03 AM by Williams, Andra P